STATE NM

	r		,	1		T
	HOLDER OF PRIMARY		NUMBER OF	HOURS OF INSPECTION	COMMODITY	
OF TRACT	TRACT INTEREST	STATUS	INSPECTIONS			TYPE
COLUMN 1	COLUMN 2	COLUMN 3	COLUMN 4	COLUMN 5	COLUMN 6	COLUMN
N00-C-14-20-5681		Aban.	1	1.5 / 3.0	Uranium	Lease
N00-C-14-20-8396	TEDCO	Aban.	1	1.5 / 3.0	Uranium	Lease
y				/		
Tess 1-10	TEDCO	Aban.	1	1.0 / 1.0	Uranium	Mining
				/		Claims
				/		
				/		
				1.		
				/		
	4		1	/	i	
BRIEF DESCRIPTIO	ON OF INSPECTION	See attachm	ment.			
IF APPROVED PLAN	I IS PENDING MODIFI	CATION, G	IVE BRIEF DES	TED OPERATOR IGINAL MINE PLAN APPROVED THE PLAN APPROVED THE PLAN APPROVED TO THE PLAN APPROVED THE PL	ATION:	
				IGINAL EXPL. PLAN API		
ATE MODIFIED EX	PL. PLAN SUBMITTEL	<u>,</u>	DATE MOI	DIFIED EXPL. PLAN API	PROVED .	
LM INSPECTOR(S)	AND TITLES(S)	George R.	Tetreault,	Jr., Mining Engineer		
URFACE MANAGEME	NT AGENCY FOR TRAC	T(S) Bu	reau of India	an Affairs		
AME, TITLE, AND	OFFICE OF SMA PER	RSONNEL PAI	RTICIPATING :	IN INSPECTION		
AME, TITLE, AND	OFFICE OF OSM OR	REGULATOR	Y AUTHORITY I	PERSONNEL PARTICIPAT	ING IN INS	PECTION
AME, TITLE, AND	OFFICE OF COMPANY	REPRESENT	TATIVE(S) PAI	RTICIPATING IN INSPE	CTION	
	TIME (PRE-INSPECT TIME (POST-INSPEC E 2	A PARK THO NO LESS DON'T USE SEASON OF SHAD	ORTING ON INS		## 2.6.198	35
AS A CONDITION (OF NONCOMPLIANCE F	ENCOUNTERE	D DURING INSE	PECTION? / YES	/xx /	NO

ERSONNEL RESPONSIBLE FOR CONDUCTING INSPECTION

IF YES, PREPARE UNDESTRABLE EVENT REPORT

MAS AN UNDESIRABLE EVENT ENCOUNTERED DURING INSPECTION? /

IF YES, PREPARE NONCOMPLIANCE REPORT

George R. Tetreault,

/ YES

/ XXX / NO

TEDCO has completed all agreed-to reclamation of the subject leases. All drill hole markers have been removed. All roads built on Haystack Mountain have been reseeded and permanently blocked by heavy boulders.

Lease -8396 was the site of the old Federal Mine operated prior to TEDCO's lease. In addition to the required reclamation, TEDCO agreed to block both adits of this mine and clean up some other areas that presented a hazard to the allottees.

Both adits have been permanently blocked and an area which water ponded, due to a collapsed stope, was reinforced to prevent such ponding in the future (see pictures).

Will conduct a gamma level study on a future inspection.